

**WEEKLY QUALITY ASSURANCE REPORT**

PAGE \_\_\_\_ OF \_\_\_\_

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls Phase 2

Installation Name: Fort Gordon, GA, USA

Contract/DO/PO Number: 24-128

Contract Number: DACA01-98-D-0024

Date: week ending March 22, 2001

(USE SEPARATE REPORT FOR Each D.O./P.O. / Contract)

**General Comments:****Work performed:**

Replaced ceiling grid on the 2<sup>nd</sup> and 9<sup>th</sup> floors.  
Painted ceiling grid on the 2<sup>nd</sup> floor.  
Replaced ceiling tile on the 2<sup>nd</sup> and 9<sup>th</sup> floors.  
Replaced exit lights on the 1<sup>st</sup> and 2<sup>nd</sup> floors.

Percent complete (if applicable) 80 %**Safety violations / Corrective measures taken:**

Safety meeting held

**Work Scheduled:****Indicate Attachments:**

% Daily QA Reports      % Schedule assessments      % Inspection Checklist      % Other  
% Safety Tool Box Meeting      % Minutes of Meetings      % Assistance provided to Facility  
Manager

Name: Lloyd South

(Printed)

US Army Corps of Engineers  
Quality Assurance Representative  
Supporting MedCom

Signature: Lloyd South